

Eaton Cooper Bussmann (UK) Ltd Melton Road Burton-on-the-Wolds, LE12 5TH United Kingdom

tel: 00 44 (0) 1509 882 600 fax: 00 44 (0) 1509 882 786

February, 2014

Dear Customer,

Subject: Products outside the Scope of RoHS Directive 2011/65/EU

In response to your request for information regarding Bussmann's compliance to the RoHS Directive 2011/65/EU, we can advise the following.

After consideration of the scope of the Directive and consultations with our trade association, BEAMA Installation Ltd, European Bodies (including the European Commission) and the DTI, we confirm that fuses and fusebases are considered as "components" and fall outside the scope of the directive.

Although fuses and fusebases currently fall outside the scope of RoHS, it is understood that the equipment which they are installed into may fall within the scope of RoHS. To the best of our knowledge we are not aware that our ranges of fuses and accessories contain any of the six substances identified in the RoHS directive, namely Lead, Mercury, Cadmium, Hexavalent Chromium, Polybrominated Biphenyls (PBB) and Polybrominated Diphenyl Ethers (PBDE) in an amount above the applicable threshold.

Kind Regards

Gareth Cooper

Technical Sales Engineer

